



**PIMA COUNTY**

**ENVIRONMENTAL QUALITY**

33 N. Stone Avenue, Suite 700  
Tucson, Arizona 85701-1429  
[www.pima.gov/deq](http://www.pima.gov/deq)

Ursula Nelson, P.E.  
Director

(520) 724-7400  
FAX (520) 838-7432

April 11, 2019

Casitas de Castilian  
Attn: Craig Denenberg  
643 W. Las Lomas Rd.  
Tucson, Arizona 85704

Re: Letter of Compliance for Casitas de Castilian, Public Water System (20-531)

Dear Water System Owner/Operator:

Enclosed is a copy of an Inspection Summary report prepared by our staff concerning the referenced facility. The inspection was performed on April 11, 2019 in accordance with Arizona Revised Statutes (A.R.S.) §49-351 et.seq. and Arizona Administrative Code (A.A.C.) R18-4-208.

No violations were observed in the operation or maintenance of this system and any previous violations have been corrected. This report addresses the system's compliance with respect to monitoring, reporting, public notice, certified operator and physical facility requirements. For information regarding those areas, please contact Pima County Department of Environmental Quality at 520-724-7400 or the Arizona Department of Environmental Quality at 602-771-9200.

Sincerely,

Rene Gomez  
Sr. Civil Engineering Assistant

cc: Pima County DEQ (file)  
ADEQ - Phoenix  
Brian Smith, Certified Operator

**PIMA COUNTY DEPARTMENT OF ENVIRONMENTAL QUALITY  
Water Program  
33 North Stone Ave., Suite 700, Tucson, AZ 85701**

**NOTICE OF COMPLIANCE - WATER**

Facility: Casitas de Castilian

System No.: 20-531

Inspected By: Rene Gomez

Inspection Date: 4/11/19

Accompanied By: Craig Denenberg and Alfonso Curiel

County: Pima

Number of EPDS's/Wells: 1 / 1

System Grade: WD1

Population: 158

Service Connections: 120

Certified Operator / Operator ID# / Operator Grade: Brian Smith, 009227, WD4

The water system is in compliance with the following ADEQ requirements:

	YES	NO	N/A
1. Monitoring.....	[X]	[ ]	[ ]
2. Reporting.....	[X]	[ ]	[ ]
3. Public Notice.....	[X]	[ ]	[ ]
4. Certified Operator.....	[X]	[ ]	[ ]
5. Physical Facilities.....	[X]	[ ]	[ ]

**SUMMARY**

As a result of the sanitary survey, your water system was found to have no deficiencies in Monitoring, Reporting, Public Notice, Certified Operator and Physical Facilities according to the requirements of the Arizona Department of Environmental Quality rules and regulations.

**System Description**

This is a community water system consisting of 1 well, 1 pressure tank and a distribution system. There is an emergency back-up connection to Tucson Water, PWS 10-112.